

Exhibit 2: Stuart Creek Fish Barrier Photographs



View of the bridge box culvert from downstream on the Stuart Creek Run property.



Close-up view of failing bridge box culvert at Stuart Creek Run taken in Fall 2008.



Exhibit 2: Stuart Creek Fish Barrier Photographs




View of the Arnold Drive box culvert taken from upstream on Stuart Creek.



View of the Arnold Drive box culvert taken from downstream on Stuart Creek.



Exhibit 2: Stuart Creek Fish Barrier Photographs



View upstream at Glen Oaks Ranch flashboard dam with 2.5-foot drop from spillway.



View from below the Glen Oaks Ranch dam downstream toward Stuart Creek Run.